


First Always Disconnect the 2 CAT5 so the Cabinet can enter in TEST mode , on the controller board there's a TEST button , press several times until the Screen is WHITE.

Common problems

1. 1 Panel Bad ( first check ribbon cable , then check power cable .
2. Cabinet flash on / off , check the power supply to see if the right voltage is selected , it should be 110 V AC



Power supply is  
5 Volts 40 Amp , and the AC should be 110  
Volts selected